

# Injectronics

## INTERIOR COMMAND CENTRE REPAIRS



The Interior Command Centre or Infotainment system began to appear in the luxury vehicle market from around the year 2000 onward, and became a standard feature of most new vehicles around 2010. If the ECM is the brains of the vehicle, then these command centres could be considered the heart. They have many functions and control systems like navigation, music or entertainment, as well as heating and cooling. Like most other electronic items, failures can occur leading to costly replacements from dealerships. Some of the common faults we have found include:

- Faulty or fading LED displays
- Damaged or cracked screens
- Touch screen has become unresponsive
- Screen remains blank
- No or distorted audio
- Buttons broken or not working correctly



Due to the age of some of these vehicles, customers have found that some replacement units are difficult to source, are no longer available from a dealership, or they can turn out to be an expensive replacement. Injectronics can offer a full repair of the Interior Command Centre, with a quick turnaround time and competitive pricing.

# Injectronics

## INTERIOR COMMAND CENTRE REPAIRS

### CHRYSLER / DODGE / FIAT



#### ICCCRYREP

Suits: Chrysler 300C /  
Dodge Journey / Fiat Freemont

### CHRYSLER / JEEP



#### ICCCJEEPREP

Suits: Chrysler 300C / Jeep Cherokee /  
Jeep Grand Cherokee

### FORD



#### ICCSYNG2REP

Suits: Ford Escape / Focus / Mondeo /  
Mustang

### FORD



#### ICCCFGNREP

Suits: Ford Falcon FG (high series) /  
Territory Titanium SZ

### FORD



#### ICCCFGLWREP

Suits: Ford FG MK1 Low series

### FORD



#### ICCCFIEFREP

Suits: Ford Fiesta WS / WZ / Ford Focus  
LW / Ford Kuga TF

### FORD



#### ICCLWFREP

Suits: Ford Focus LW / Ford Kuga TF

### HOLDEN



#### ICCCAPHREP

Suits: Holden Captiva CG

### HYUNDAI



#### ICCCACCHREP

Suits: Hyundai Accent RB / RB2

CALL 1300 308 050 FOR FURTHER ASSISTANCE  
OR VISIT [INJECTRONICS.COM.AU](http://INJECTRONICS.COM.AU)

# Injectronics

## INTERIOR COMMAND CENTRE REPAIRS

### HYUNDAI



#### ICCELAHREP

Suits: Hyundai Elantra MD2 / MD3

### HYUNDAI



#### ICCI30HREP

Suits: Hyundai i30 GD infotainment stereo unit

### HYUNDAI



#### ICCI30H1HREP

Suits: Hyundai i30 GD Navigation unit

### HYUNDAI



#### ICCILOHREP

Suits: Hyundai iLoad TQ

### HYUNDAI



#### ICCI35HREP

Suits: Hyundai iX35 LM infotainment stereo unit

### HYUNDAI



#### ICCI35H1REP

Suits: Hyundai iX35 LM Navigation unit

### LEXUS



#### ICCLEXREP

Suits: Lexus IS250 / IS350

### MITSUBISHI



#### ICCOUTREP

Suits: Mitsubishi Outlander ZJ

### VOLKSWAGON



#### ICCVW1REP

Suits: VW Jetta 1B / Passat 3C / Golf 7 / Golf 6R

CALL 1300 308 050 FOR FURTHER ASSISTANCE  
OR VISIT [INJECTRONICS.COM.AU](http://INJECTRONICS.COM.AU)



# Injectronics

## **ICCDIR6150REP** Mitsubishi Fuso truck (2014-2018)

Not only can Injectronics repair ICC units for passenger cars, we also offer the same repairs for trucks and heavy duty vehicles. This unit comes from a Mitsubishi Fuso truck (2014-2018).

This unit has the following common faults:

- Touchscreen display not functioning
- Volume not adjusting
- Screen cracked or damaged
- No display / blank screen
- CD won't play
- Disc jammed



## **ICCFGREP** Ford Territory SZ Series (2011-2016) / Ford Falcon FG MKII (2011-2014)

This repair is for the non-navigation type unit for both vehicles. The screen must be separated from the ICC and shipped for repair. Please note – Injectronics need additional information about the vehicle before attempting this repair. Common faults include:

- Screen frozen on start-up image
- Blank screen
- Buttons inoperative
- Lines across screen



## **ICCDIR4850REP** UD PK 16 250 (2012-2014)

Yet another HD repair to add to the list. Injectronics have seen numerous units from these UD trucks. Common faults can include:

- Touchscreen not working
- Volume not adjusting
- Screen cracked or damaged
- No display
- CD will not play
- Disc jammed



## **ICCRG1REP** Holden Colorado RG (2013-2016)

Another popular repair is for the Holden Colorado. Common faults associated with this unit include:

- No screen operation
- Touch screen not working
- Audio output distorted

