

Injectronics

Remanufactured Automotive Electronics Components

PRODUCT SERVICE INFORMATION

Document number: P0007

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Vehicle: BMW - E32 (7 Series) and E34 (5 Series up to 1989)

Subject: Dash cluster display

To change display languages on BMW E32 – 7 Series and E34 – 5 Series dash cluster up to 1989, the following needs to be done:

1. Turn key to accessory position only
2. Hold in menu button (located on left hand side of dash) for approx. 10 Seconds, until a language version is displayed
3. If the one displayed is not the one required, release button and then depress again for approx. 10 seconds until the next language is displayed.
4. Continue this until correct language is displayed and then turn off key.

Injectronics provides an exchange back board for these models, common problems include:

- Chime continually sounding
- No fuel, temp or tacho gauges
- Chime sounding when applying brakes



P0007.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.