

# Injectronics

Remanufactured Automotive Electronics Components

## PRODUCT SERVICE INFORMATION

Document number: P0032

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit [www.injectronics.com.au](http://www.injectronics.com.au), call our office on (+613) 8792 6999, or email [sales@injectronics.com.au](mailto:sales@injectronics.com.au)

Vehicle: Audi A4 (1995-1996)

Subject: Climate controls

Note: Suits models with dual display climate control. Part number beginning with 8D0820043

These climate control units need to have the correct variant coding programmed into unit when installed. This can be read from the original unit or be obtained from Audi. This is done to cover the variations in vehicle options and engine types.

After replacing the climate control, always:

- Check coding or enter new coding
- Perform basic settings
- Check / clear any fault codes

Most after-market scan tools can perform the above functions. Failure to do the above can result in faulty operation including:

- AC light not staying on after pressing button
- Fault codes which cannot be cleared.



P0032.doc